



ColorWash 1200E ^{AT}

Photometric Diagrams



FRESNEL LENS

Lamp: MSR 1200 SA



Beam angle 10°- LightMax Mode



Beam angle 13°- Min. zoom



Beam angle 44°- Max. Zoom





ColorWash 1200E ^{AT}

Photometric Diagrams



PC LENS

Lamp: MSR 1200 SA

Beam angle 10°- LightMax Mode



Beam angle 12°- Min. zoom



Beam angle 36°- Max. Zoom

